

## INDUSTRIAL PAINTING AND COATING APPLICATION

**"Without the skills and safety training of our IUPAT workforce, working in the air suspended from ropes could have cost lives. Instead, we didn't have a single recordable injury in the stadium."**

*Bob Souchuck, Corporate Quality Control and Safety Director  
Champion Specialty Services Corp.*

**Location:** Atlanta, Georgia

**Opened:** 2017

**Owner:** Georgia World Congress Center Authority

**Key Tenants:** Atlanta Falcons, Atlanta United

**Architect:** HOK, tvsdesign, Goode Van Slyke, Stanley Beaman & Sears

**Project Manager:** Darden & Company

**General Contractor:** HHRM, JV

**Structural Engineer:** BuroHappold Engineering/Hoberman

**Services Engineer:** WSP

**Industrial Painting:** Champion Painting Specialty Services Corp.

**Size:** 2,000,000 sq. ft., 30 stories

**Seats:** 71,000, expandable to 75,000

**Total Structural Steel:** 27,000 tons

**Scope of Work:** Clean and put 3-coat systems on all weld, nut and bolt connections.

## MERCEDES-BENZ STADIUM

Prime, prep and coat every connection in 27,000 tons of steel. **While suspended from the air.**



This \$1.5 billion stadium, host of the 2019 Super Bowl, pushes every design boundary. A 16-story window soars on one side, while eight triangular steel and glass sections form the rest of the LEED platinum stadium. It's also a technological wonder, with fully interactive game-day experiences that include the world's largest video screen. But its most unique feature is the stunning retractable roof, with multiple panels that slide open like a camera aperture to resemble a falcon wing.

Champion Specialty Services Corp. (Champion) was selected to clean and apply 3-coat systems on every weld, nut and bolt connection in the stadium's 27,000-ton steel skeleton to prevent corrosion and extend the stadium's longevity.

### The Challenge

Originally, 90% of Champion's work was to be done on the ground, with 10% aerial. But since the steel skeleton was erected early and was too angular for cranes, 100% of the work needed to be done using rope access. This meant the entire process had to be quickly refigured. And the structure was so complex, the steel network holding up the roof and video board alone had 850,000 bolts. Also, an accidental omission in the construction schedule meant Champion couldn't bring in all the necessary equipment.

### The Solution

After initially hiring an IUPAT rope access crew from Canada, Champion soon formed their own specialized rope access team. To meet the project schedule and have access to all the equipment they needed, Champion collaborated closely with other trades, who let them use their equipment at night. The team worked 16-hour double shifts for two years to complete the project on time, against all odds.

### The IUPAT Industry Partner Advantage

"Most everyone in our company is an IUPAT member, so even management has that intense training to know what it takes," states Bob Souchuck, Corporate QC and Safety Director of Champion Painting, a Florida-based specialty coating company. "And the certifications we achieve through IUPAT are crucial to being invited to bids. In fact, there are only a handful of Master Coatings Inspectors in North America, and we have two of them."